

LISTE DES COMPOSANTS DU VFO

TRANSISTORS

BF 245	x2	
2N 2222	x1	
J310	x1	
7808	x1	alimentation
7809	x1	alimentation

TORES FERRITE

T50-6	x1	
T37-2	x2	

DIODES

1N 4148	x1	
BB 112	x1	

CAPA

47 MF 25V	x3	alimentation
10 PICOT AJUST	x1	
65 PICOT AJUST	x2	
220 NANO	x4	alimentation
47 NANO	x3	
100 NANO	x8	
10 NANO	x2	
100 PICOT	x1	
47 PICOT NPO	x3	
180 NANO STIRO	x1	
220 PICOT STIRO		

POTENTIOMETRE

10 K 10 TOURS	x1	
---------------	----	--

RESISTANCES 1 / 4 W

100 K	x2	
47 K	x2	
4,7 K	x1	
10 K	x1	
1 K	x1	
8 K	x1	
270 HOMS	x1	
100 HOMS	x2	
47 HOMS	x1	
10 HOMS	x1	